
Footpath usage survey – 2024: Findings






Harshad Abhyankar Harshad.abhyankar@savepunetraffic.org

Save Pune Traffic Movement



There is something wrong with a footpath if people are still walking on the carriageway!	 Important KPI of a footpath: Pedestrians must use it! Objective 1: What % of people are still walking on the road? "People just don't use a footpath" Why would someone want to put their life in danger, intentionally? Objective 2: Identify salient features that encourage / discourage people from using footpath Photo documentation 	
--	--	--



5

Usage: 7% Opposite

Pedestrians need to go up-n-down, but there's huge space to park perpendicularly! Only 7% peds are on this 'footpath' opp Radisson, Kharadi. On the right, you can see the extent of the dirt line. There is ample scope to build a well designed JM-FC-like FP here.



Usage: 23%

This Vimannagar footpath offers more obstructions to walk, than the carriageway. No wonder only 23% pedestrians were found using it! Widen it just by a meter and these ladies would walk safely. Vehicular flow wouldn't be affected!

Viman Nagar



Usage: 35% Fatimanagar

This footpath in Fatimanagar treats pedestrians like second class citizens. Huge space is provided for parking! This lady + son would have walked on the FP if it were wide enough to push parking in the same line as the tree. Result? Only 35% peds use the footpath.



Usage: 49%

A dead wall, parked vehicles, DP boxes create a claustrophobic realm for pedestrians. No wonder 49% peds were found using the carriageway of Shahu College Rd. Widen FP by a meter, remove parking. All peds will be on FP then, and traffic also will be smoother!

Shahu College Rd



Usage: 56% Amrut Ganga Soc., off Sinhagad Rd

Barricades cut pedestrians off, and make the footpath feel unsafe, inconvenient. Why do you need such barricades? Only 56% pedestrians were found using this footpath at Amrut Ganga Society, off Sinhagad Rd.



Usage: 57%

Only 57% pedestrians walk on this footpath near 7 Loves. This FP also could have been wider by one more meter. Pedestrians must be given the space they need! If you are worried about 'bechare vehicles', the dirt line tells you how much space vehicles use/need!

Nehru Road, near Seven Loves



10

9

Usage: 79%

Loop Rd has an example of a footpath that is not super-wide, but provides a clear, uninterrupted walkway. 79% peds are on the FP here. Yet, just one more meter would put the guy in the checkered shirt on the footpath, instead of walking next to moving vehicles.

Loop Road



Usage: 79%

This footpath on Bibwewadi-Kondhwa Rd provides a clear, uninterrupted walkway. 79% pedestrians were on FP! But it could have been easily wider by about a meter, even without affecting parking (See the yellow marks). We are sure that would have put nearly 100% pedestrians on the FP.

Bibwewadi-Kondhwa Rd



12

11

<text><text><text><text>

13

Usage: 91%

As many as 91% pedestrians were found using this 'footpath' at Wakdewadi ST Stand! What you see here is a cycle track, adjacent to a 'footpath' that is occupied by illegally parked vehicles. Don't the traffic police see these vehicles parked on the footpath?

At Wakdewadi ST Stand



14